

SUMMARY OF OCTOBER 2008 REVISIONS - VERSION 3.1.3.2

Since the release of BRADD Version 3.1.3.1, an issue with the bearing offsets has been reported. See e-Notification 019. This patch release of BRADD Version 3.1.3.2 contains the following revision:

1. Corrected calculations of bearing offset values at Abutment 2 to properly consider box beam transverse slope for spread and adjacent box beam bridges. Corrected calculations of bearing offset values at Abutment 1 and 2, and membrane waterproofing quantities to include the sole plate thickness. The changes to the bearing offsets due to the sole plate thickness are very small, in the third decimal place (for example, 0.003). The change in the membrane waterproofing quantity due to the sole plate thickness could add additional square yards to the quantity. (vi:3438)