

SUMMARY OF FEBRUARY 2018 REVISIONS - VERSION 3.2.4.1

Since the release of BRADD Version 3.2.4.0, a minor operational issue has been reported concerning the integral abutment details: Abutment Plan @ Top of Deck, Abutment Plan @ Pile Cap, and Elevation. See e-Notification 048. This patch release of BRADD Version 3.2.4.1 contains the following revision:

1. For skewed bridges that have integral abutments and staged construction with different beam spacings left and right of the construction joint, the length of the integral abutment detailed by BRADD did not account for the skew of the bridge. These problems have been resolved. (TFS-5456)